

## Make a supercapacitor – RISK ASSESSMENT

<b>Hazard</b>	<b>Likelihood and Seriousness of Injury</b>	<b>Control measures</b>	<b>Assessment of remaining risk</b>
<b>Handling scissors</b>	Possible, serious injury unlikely	Careful handling. Any cuts should be washed with plenty of water.	Low
<b>Use of activated charcoal</b>	Possible, serious injury unlikely	Avoid inhalation and insertion in eyes due to small particle size.	Low